

# Spa Cover Rocker

## INSTRUCTIONS

### PARTS LIST

DESCRIPTION	QTY
A. Under-Mount Base Brackets	2
B. Bottom Pivot Arms	2
C. Support Crossbar Arms	2
D. Center Extension (1 Fluted)	2
E. Self Tapping Screws	15
F. Plastic Pivot Caps	4
G. Black Plastic Caps	4
H. Hex Screws	2
I. Flat Washer	4
J. Nuts	2
K. Small Black Plastic Caps	15




Figure 1

**1** Position your spa cover in the closed position with all four corners evenly matched with the spa corners.

**2** Connect the **Pivot Arm (B)** to a **Plastic Pivot Cap (F)** on each side of the hole (flat side out). Next, connect the **Pivot Arm (B)** to the **Under-Mount Base Bracket (A)** with a **Washer (I)** & **Hex Screw (H)**. Attach **Plastic Caps (G)**. See Figure 1. Repeat on the other side.

**3** Slide the both **Under Mount Base Brackets** under the spa with the **Pivot Arms (B)** in the upright position. *Note: The edge of the Base Bracket should be 7" for the edge of the spa.* See Figure 2.





Figure 2



4

Insert the LONG end of the **Crossbar Support Arms (C)** into the **Pivot Arms (B)**. Next, use the non-fluted **Center Extension (D)** to connect the **Support Arms (C)**. To add length, use the fluted **Center Extension (D)**. See Figure 3.

5

Lay the assembled **Cover Rocker** on the closed spa cover. Adjust **Support Arms (C)** & **Center Extensions (D)** so that the **Support Arms (C)** are 1/2" away of the center of the cover fold. See Figure 4.

6

Use the **Self-Tapping Screws (E)** to secure the **Pivot Arms (B)**, **Support Arms (C)**, & **Center Extensions (D)** together.




Figure 3




Figure 4

## PRO TIP

When using both **Center Extensions (D)**, rotate extensions so that the **Self-Tapping Screws (E)** are positioned at the same angle to the **Support Arms (C)**. Doing this action will prevent the screws heads from damaging the spa cover during operation of the Cover Rocker.

**CAUTION: DO NOT USE THE COVER LIFT IN HIGH WIND CONDITIONS. DOING SO COULD CAUSE THE COVER TO FALL. DAMAGE TO THE SPA COVER/COVER LIFT, OR INJURY TO THE OCCUPANTS MAY OCCUR. NEVER LEAVE AN UNCOVERED HOT TUB OR SPA UNATTENDED.**